EX PARTE OR LATE FILED

April 23, 1997

RECEIVED

APR 2 3 1997.

Federal (Sission Williams to Continuency

William F. Caton **Acting Secretary** Federal Communications Commission Room 200, 1919 M Street, NW Washington, D.C. 20554

> Re: Ex Parte Notification Docket No. 94-102

Dear Mr. Caton:

The purpose of this letter is to notify the Commission, pursuant to Section 1.1206(a)(2) of the Commission's Rules, that on April 22, 1997, the following parties listed below met with John Cimko, Dan Grosh, Ron Netro, Nancy Boocker, Steve Weingarten and Won Kim of the Federal Communication Commission's Wireless Bureau.

The parties included: Mary Madigan of the Personal Communications Industry Association (henceforth referenced as PCIA); Craig Krueger of PCIA; Barbara Baffer of Ericsson; Ben Almond of BELLSOUTH; Gina Harrison of Pacific Telesis; Mary Brooner of Motorola; Gary Jones of Omnipoint; Terri Brooks of Nokia Telecommunications Inc.; Thomas C. Blum of Bell Atlantic NYNEX Mobile; Jeremy Pemble of Siemens.

The parties discussed issues relating to the E-911 proceeding, Docket No. 94-102. The enclosed attachment was distributed to all parties attending this ex parte meeting. This attachment provides a summary of the issues discussed at this ex parte meeting. Should you have any questions regarding the matter, please call me.

Respectfully submitted

Craig A. Krueger

Manager Government Relations-Federal Affairs

No. of Copies rec'd

Wireless 911 Coalition

■ Bell Atlantic NYNEX Mobile, BellSouth, Ericsson, Motorola, Nortel, Nokia, Omnipoint, Pacific Bell Mobile Services, PrimeCo Personal Communications, PCIA, Siemens

Wireless 911 Coalition

- Preliminary TTY Testing
- E911 Access
- Other PFR Issues

- Phase 1: Joint Industry Testing
- Joint testing Session No. 1: Siemens, Nortel, Ericsson
- Status: Complete

- Joint Test Session No. 2
- Siemens, Nortel, Ericsson plus Nokia and Motorola
- Scheduled for April 24 or 25

- Key Issue: Does the vocoder in the handset distort the TTY signal?
- Manufacturers agreed to focus on direct connection through the audio path (as opposed to treating the TTY signal as a data call).
- Results from Joint Session Number 1 were mixed
 - Further research required

- If it is determined that vocoders do not distort the TTY signal, it will be feasible to develop a direct cable from the handset:
 - –2.5 millimeter connection in the TTY, or
 - –a cable/box-like unit to the RJ11 in the TTY

E911 Access

Definition of code identified should be based on mobile directory number.

The Proposed Definition of "Code Identified":

A unique identifier from which the directory number (if any) associated with a mobile unit may be derived. The directory number may be derived directly from the code identifier (e.g. MIN) or via a database lookup (e.g. IMSI). The code identifier may be assigned to a mobile unit or may be assigned to an inserted User Identify Module (UIM).

Code Identification Issues

Situation	Contributing to Enhanced 911 Capability	Code Identified ¹	Service Initialized/ Mobile Directory Number	Set Uniquely Identifiable/ Callback Capability
New handset, just out of the box	No	Yes	No	No
Disconnected handset, number not yet reused	No	Yes	No	Yes/No
Disconnected handset, number reassigned to new subscriber	No	Yes	No	No
Cloned handset	No	Yes	Yes	No
Handset w/only 911 capability	No	Yes	No	No
Handset from any new or current customer of any wireless carrier	Yes	Yes	Yes	Yes

¹ Our interpretation of "Code Identified" seems to indicate that any handset which contains any Mobile Identification Number (MIN) or International Mobile Subscriber Number (IMSI), whether associated with a subscriber or not, can be viewed as being Code Identified. A MIN or IMSI must exist in a handset for the network to recognize and facilitate a call from that handset to Customer Service or Service Initialization Center. This MIN or IMSI can be any combination of digits such as all 0's or all 9's, both of which are typically preprogrammed in new sets. When service is initialized, the MIN or IMSI is changed to be actually the subscriber's mobile directory number or to be associated with the subscriber's mobile directory number, in the case of IMSI.

Code Identification Issues

The FCC's definition of code identification is unworkable when applied to a variety of possible handset situations and when considering the desires and expectations of public safety agencies. The following are six examples of "real world" handset situations which must be addressed by CMRS carriers to meet October 1, 1997 requirements.

- 1. New handset, just out of the box This type handset has been purchased (or taken) from a retail center but has not been service initialized by any CMRS provider. Typically, these handsets are pre-programmed with default values in the MIN/IMSI based field to facilitate initialization. However, the default values do not represent valid directory numbers therefore calls cannot be made except possibly to a CMRS provider's customer service center.
- 2. Disconnect handset, number not yet reused This set was previously provided a directory number when the user subscribed to wireless service. Although service has since been disconnected, the directory number still remains programmed in the handset. In today's environment, any calls to or from this set would be blocked by the carrier.
- 3. Disconnected handset, number reassigned to new subscriber A handset in this category would not be able to receive or make calls. The old directory number would still reside in the set, however, the carrier's validation database would not recognize the old set as valid because the directory number would now be associated with a new handset. A call made to this number would only ring the new handset.
- 4. Cloned handset This is a handset which has been illegally altered to allow it to make calls using another handset's valid subscription. It cannot make or receive calls when the other handset is in use.
- 5. Handset with only 911 capability These sets are typically sold in specialty stores and through catalogs. They can only make calls to 911 and cannot receive calls.
- 6. Handset from any new or current customer of any wireless carrier- These sets are commonly referred to as "service-initialized" sets. They are recognized as valid subscribers by their carrier and thus can make and receive calls.

Code Identification Issues

Based on our interpretation of the FCC's definition of code identification and its requirements to pass all code identified calls without validation, our matrix identifies a number of problems for PSAPs and our wireless customers.

- Only service initialized handsets will be contributing to the costs of wireless 911.
- PSAP call back to disconnected numbers or cloned phones may not reach the intended caller.
- PSAP call back is not possible to handsets which have not been assigned a unique directory number.
- PSAPs will not be able to trace prank or threatening calls unless the caller is a valid subscriber.

E911 Access




- No call-back capability number one priority for PSAPs
- High likelihood of fraudulent and prank calls - no danger of identification

PSAP Choice of Call Acceptance

- Allowing PSAPs to choose whether or not they will accept calls from non-code identified handsets is problematic.
 - Technical considerations
 - Administrative considerations
 - Liability issues
 - Customer confusion

Overlapping Radio Coverage



Extended Radio Coverage

